[圧力]の種類を以下に示す。0,100
Selection of pressure sensor types, to be entered in "[圧力(Pressure)]" as the model, is shown as follows: 0, 100

[電源]の種類を以下に示す。BT、AC、DC
Selection of power supply types, to be entered in "[電源(power supply)]" as the model, is shown as follows: BT, AC, DC

BT,DCのみCEマーキング有
CE marking is applied for BT and DC types only.







No	D1	D2	C
1			
2			
3			
4			
5			／
6			／
7			／
8		／	／
9		／	／
10		／	／
11		／	／
12		／	／
13		／	／
14		／	／
15		／	／
S			

UX50-[圧力][電源]-L
型式 MODEL

尺度 SCALE	年月日 DATE	名称 NAME	図番 DRAWING NUMBER
	2020/02/25	High-performance Ultrasonic Flowmeter for Fuel Gas	UX50-[圧力][電源]-L

Aichi tokei denki co., ltd.