


|  |   |  |        |   |
|--|---|--|--------|---|
| <br>Reliability<br>Creativity Service | <b>Product Specifications</b>   |  | Ver. 4 | 1/6   |
|  | <b>Ultrasonic Flow Meter for Air<br/>(External Power Supply Type)</b> |  | Model  | TRX [Nominal diameter] D / [Gas type] / 5P / [Degreasing process] |

## 1. Specifications

⊙ Model TRX [Nominal diameter] D / [Gas type] / 5P / [Degreasing process]

| Nominal diameter                  | Gas type                                 | Degreasing process                                   |
|-----------------------------------|--|--|
| <input type="checkbox"/> 25 (25A) | <input type="checkbox"/> C (factory air) | <input type="checkbox"/> No description (no process) |
| <input type="checkbox"/> 32 (32A) | <input type="checkbox"/> N (nitrogen)    | <input type="checkbox"/> K (degreasing process)      |
| <input type="checkbox"/> 40 (40A) |  |  |
| <input type="checkbox"/> 50 (50A) |  |  |
| <input type="checkbox"/> 65 (65A) |  |  |
| <input type="checkbox"/> 80 (80A) |  |  |

Flow-rate range (Actual flow-rate) (Accuracy guaranteed scope)

|                 | [m <sup>3</sup> /h] |            |            |             |           |           |
|-----------------|---------------------|------------|------------|-------------|-----------|-----------|
| Model           | TRX25               | TRX32      | TRX40      | TRX50       | TRX65     | TRX80     |
| Flow rate range | ±0.6 to 35          | ±1.1 to 65 | ±1.3 to 80 | ±2.5 to 150 | ±4 to 240 | ±5 to 300 |

Accuracy (Actual flow-rate)

- Flow-rate measurement accuracy

|          | [m <sup>3</sup> /h] |             |             |           |            |            |            |
|----------|---------------------|-------------|-------------|-----------|------------|------------|------------|
| Model    | TRX25               | TRX32       | TRX40       | TRX50     | TRX65      | TRX80      |            |
| Accuracy | ±5%RD               | ±0.6 to 3.5 | ±1.1 to 6.5 | ±1.3 to 8 | ±2.5 to 15 | ±4 to 24   | ±5 to 30   |
|          | ±2%RD               | ±3.5 to 35  | ±6.5 to 65  | ±8 to 80  | ±15 to 150 | ±24 to 240 | ±30 to 300 |

- NORMAL conversion

± 2.5%RD (0.5MPa, ordinary temperature and, dry air or nitrogen)

Low flow cutoff (Actual flow rate) Can be Changeable by button operation (0 ≤ Setting value < Qmin)


|                       | [m <sup>3</sup> /h or less] |       |       |       |       |       |
|-----------------------|-----------------------------|-------|-------|-------|-------|-------|
| Model                 | TRX25                       | TRX32 | TRX40 | TRX50 | TRX65 | TRX80 |
| Initial setting value | ±0.1                        | ±0.2  | ±0.2  | ±0.4  | ±0.6  | ±0.8  |

Response-ability Update interval : 0.5 second

Smoothing of instantaneous flow rate value by moving average method (Initial setting value: 4 times)

"⊙" is selectable item.

-

|   |   |       |   |     |
|---|---|-------|---|-----|
|  | <b>Product Specifications</b>   |       | Ver. 4  | 2/6 |
|   | <b>Ultrasonic Flow Meter for Air<br/>(External Power Supply Type)</b> | Model | TRX [Nominal diameter] D / [Gas type] / 5P / [Degreasing process] |     |

**Display**

Main display: The following is switched and selected using the “left button”.

[When forward flow display mode \*1) is selected]

Accumulated flow volume (Forward flow) (m<sup>3</sup>)·Trip accumulated flow volume (Forward flow) (m<sup>3</sup>)·Instantaneous flow-rate (L/min)\*2)

[When reverse flow display mode \*1) is selected]

Accumulated flow volume (Forward flow) (m<sup>3</sup>)·Accumulated flow volume (reverse flow) (m<sup>3</sup>)·Instantaneous flow-rate (L/min)\*2)

Sub display: The following is switched and selected using the “right button”.

Instantaneous flow-rate (m<sup>3</sup>/h)·Pressure (kPa) (gauge pressure)·Temperature (°C)

\*1) The display mode is selected by button operation.

\*2) If an instantaneous flow-rate (L/min) is displayed, the main display (Accumulated flow rate) and sub display (Instantaneous flow rate (m<sup>3</sup>/h) , pressure (kPa) and temperature (°C)) are not displayed.

**Number of digits displayed**

**Main display**

|  |   |             |          |
|--|---|-------------|----------|
| Accumulated flow volume (Forward flow) [m3]    | : | 00000000.0  | 9 digits |
| Trip accumulated flow rate (Forward flow) [m3] | : | ┆ 0000000.0 | 8 digits |
| Accumulated flow rate (Reverse flow) [m3]      | : | -0000000.0  | 8 digits |
| Instantaneous flow rate [L/min]                | : | 00000.00    | 7 digits |

Unit: Selected by button operation and communication

| When NORMAL flow is selected | When standard flow is selected | When actual flow is selected |
|------------------------------|--------------------------------|------------------------------|
| m <sup>3</sup> (NORMAL)      | m <sup>3</sup> (Standard)      | m <sup>3</sup>               |

Note) In case actual flow display (m<sup>3</sup>) is selected for "accumulated flow volume (forward flow)", "trip accumulated flow volume (Forward flow)", and "accumulated flow volume (Reverse flow)", it is displayed to the second decimal point.

**Sub display**


|  |          |
|--|----------|
| Instantaneous flow-rate [m <sup>3</sup> /h]: 000.00 (less than 1000) | 5 digits |
| 0000.0(1000 or more and less than 10000)                             | 5 digits |
| 00000 (10000 or more)  | 5 digits |

Unit: Selected by button operation

| When NORMAL flow is selected | When standard flow is selected | When actual flow is selected |
|------------------------------|--------------------------------|------------------------------|
| m <sup>3</sup> (NORMAL)      | m <sup>3</sup> (Standard)      | m <sup>3</sup>               |

Pressure [kPa]: 0000.0 5 digits

Temperature [°C]: 00.0 3 digits

|   |   |        |   |
|---|---|--------|---|
|  | <b>Product Specifications</b>   | Ver. 4 | 3/6   |
|   | <b>Ultrasonic Flow Meter for Air<br/>(External Power Supply Type)</b> | Model  | TRX [Nominal diameter] D / [Gas type] / 5P / [Degreasing process] |

Electric current output Output method : 4-20 mA Two-wire type  
Power supply voltage : 24 VDC±10% Power consumption: 0.6 W or less  
Output accuracy : ±0.5%FS  
External load : 400 Ω or less

("Instantaneous flow-rate", "Pressure", and "Temperature" can be switched by button operation.)

When instantaneous flow-rate is selected

[Forward flow display mode]

Zero output current : 4.0 mA (Reverse flow to low flow cutoff)  
Output current lower limit : 4.0 mA (Clip at 4.0 mA)  
Output current upper limit : 22.0 mA (Clip at 22.0 mA)

[Forward/reverse flow display mode]

Zero output current : 12.0 mA (Within low flow cutoff)  
Output current lower limit : 3.5 mA (Clip at 3.5 mA)  
Output current upper limit : 22.0 mA (Clip at 22.0 mA)

Full scale flow rate (Can be changed by button operation)


| Model                 | TRX25 | TRX32 | TRX40 | TRX50 | TRX65 | TRX80 |
|-----------------------|-------|-------|-------|-------|-------|-------|
| Initial setting value | 300   | 600   | 700   | 1200  | 2000  | 2500  |

When pressure is selected

Output method : Output as 4.0 mA: 0 MPa, 20.0 mA: 1 MPa (Fixed)  
Output current lower limit : 4.0 mA (Clip at 4.0 mA)  
Output current upper limit : 22.0 mA (Clip at 22.0 mA)

When temperature is selected

Output method : Output as 4.0 mA: -10°C, 20.0 mA: +60°C (Fixed)  
Output current lower limit : 3.5 mA (Clip at 3.5 mA)  
Output current upper limit : 22.0 mA (Clip at 22.0 mA)

|   |   |  |        |   |     |
|---|---|--|--------|---|-----|
|  | <b>Product Specifications</b>   |  | Ver. 4 |   | 4/6 |
|   | <b>Ultrasonic Flow Meter for Air<br/>(External Power Supply Type)</b> |  | Model  | TRX [Nominal diameter] D / [Gas type] / 5P / [Degreasing process] |     |

Contact output Open drain output 2 channels

Output 1 : Unit pulse output (Forward flow)  
Output 2 : Unit pulse output (Reverse flow), flow rate upper and lower limit alarm output, body error output, telegram output  
(Either one is selected by button operation)  
Maximum load : 26.4 VDC·50 mA  
Saturated voltage when ON : 1.5 V or less  
Current when OFF : 50 μA or less

**Pulse output**

Unit pulses in accordance with increase of the accumulated flow volume are output.  
Pulse unit : 100 L/P (Initial setting value)  
(Can be changed by button operation)  
Maximum output frequency: 10 Hz  
Output type : One shot or duty (Can be changed by button operation)  
One shot pulse width : 50, 100, 125, 250, 500 ms (Can be changed by button operation)  
Duty : 35 to 65%

**Flow-rate upper and lower limit alarm output**

When the instantaneous flow-rate becomes higher or lower than the set flow rate, an alarm signal is output.  
(The alarm output upper and lower limit flow rate and alarm judgment value hysteresis width can be set by a button operation.)

**Body error output**

An alarm signal is output when a flow-rate measurement error, pressure value error, temperature value error or communication circuit error is detected.


**Telegram statement**

Measurement data are transmitted using telegrams at regular time intervals (10 minutes)  
Telegram type: Asynchronous 2400 bps  
Transmitted data: Accumulated flow volume (Forward flow), accumulated flow rate (Reverse flow), instantaneous flow rate, pressure, temperature and error information

Measurable fluid : Air (Mainly factory air) or nitrogen  
Working fluid temperature : -10 to +60°C, 90%RH or less  
Working pressure : 0 to less than 1MPa (Gauge pressure)  
Working environment : -10 to +60°C, 90%RH or less (There must be no condensation)  
Storage environment : -20 to +70°C (There must be no condensation)  
Power supply : 24 VDC±10% Power consumption: 1.5 W or less  
Flow direction : Forward and reverse flows can be measured (Direction indicated by the arrow is forward flow.)

|                 |                 |                              |       |   |       |       |       |
|-----------------|-----------------|------------------------------|-------|---|-------|-------|-------|
| Connection type | Model           | TRX25                        | TRX32 | TRX40   | TRX50 | TRX65 | TRX80 |
|                 | Connection type | Taper pipe thread (Screw-in) |       | Wafer<br>(Installed and tightened between JIS10K flanges) |       |       |       |

Installation position : Horizontal (LCD display portion faces upward) or vertical  
Pressure drop : Extremely low (Equivalent to a straight pipe)  
Protection structure : IP 64(JIS C0920: dust-proof, splash-proof type) which can be installed outdoors

|   |   |       |   |     |
|---|---|-------|---|-----|
|  | <b>Product Specifications</b>   |       | Ver. 4  | 5/6 |
|   | <b>Ultrasonic Flow Meter for Air<br/>(External Power Supply Type)</b> | Model | TRX [Nominal diameter] D / [Gas type] / 5P / [Degreasing process] |     |

**Mass**

|       |        |        |        |        |        |        |
|-------|--------|--------|--------|--------|--------|--------|
| Model | TRX25  | TRX32  | TRX40  | TRX50  | TRX65  | TRX80  |
| Mass  | 1.5 kg | 1.4 kg | 1.0 kg | 1.2 kg | 1.4 kg | 1.7 kg |

**Material**

- Measurement portion : Engineering plastic (Such as PPS), aluminum alloy
- Outer casing : Aluminum alloy
- Sensor rubber : FVMQ (Fluoro silicone rubber)

Display portion casing : Aluminum alloy

\*○ symbol indicates the gas contacting parts.

In the case of a degreasing process product, a degreasing process has been performed for gas contacting parts.

(For details, refer to “3. Degreasing process”.)

Standard working period 10 years (at ambient temperature of 20°C and ambient humidity of 65%RH)

\* 10 years is not the warranty period.

**Accessories**

- M4 Hexagonal wrench
- Centering collar (Wafer type only)
- Flange gasket (Wafer type only)
- Bolt set (Wafer type only)

Power supply / output cable (Six-core cable) [option]

⊙ Cable length:  5 m     20 m


Wire connection:

|                       |        |
|-----------------------|--------|
| Open drain output 1   | White  |
| Open drain output 2   | Yellow |
| 4 to 20 mA output (+) | Red    |
| 4 to 20 mA output (-) | Green  |
| Communication ····    | Brown  |
| GND ···········       | Black  |

"⊙" is selectable item.

**Others**

CE marking, UKCA marking, RoHS Directive compliant

|   |   |       |   |     |
|---|---|-------|---|-----|
|  | <b>Product Specifications</b>   |       | Ver. 4  | 6/6 |
|   | <b>Ultrasonic Flow Meter for Air<br/>(External Power Supply Type)</b> | Model | TRX [Nominal diameter] D / [Gas type] / 5P / [Degreasing process] |     |

## 2. Precautions in handling

### 2-1. Installation environment

- (1) Although the high weather-proof electronic display is adopted, in case of installation at a place subjected to direct .
- (2) Do not install the flow meter at a place with much electromagnetic noise or in corrosive atmosphere.
- (3) This product is designed for outdoor installation, but avoid areas where there is a risk of water submergence and water always splashes.
- (4) When opening or closing a valve before and after the flow meter, open or close the valve not all at once but gradually.

### 2-2. Piping conditions

- (1) To realize stable measurement, it is recommended to install a straight pipe portion of 20 D or more (D: nominal diameter) at the upstream and downstream sides of the flow meter.
- (2) In case large amount of mist, dust, etc., are contained in the fluid, install the flow meter by vertical piping. In the case of horizontal piping, install the flow meter so that the display part faces upward.
- (3) In case installation of the product near a pressure reducing valve or a flow adjusting valve is planned, contact us in advance.

## 3. Decreasing process

In the case of a degreasing process product, the followings are the degreasing processes for the gas contacting parts.

- (1) Ultrasonic cleaning degreasing process by degreasing cleaning liquid  
For gas contacting parts (Other than the following specified parts), after immersion in degreasing cleaning liquid and performing ultrasonic cleaning, the cleaning liquid attached to the parts surfaces are to be removed with tap water (Running water).
- (2) Degreasing process by alcohol wiping  
After wiping the following specified parts with hand towels containing alcohol, they are wiped again with hand towels containing tap water.

<Specified parts>

Ultrasonic sensor, pressure sensor unit's pressure introduction portion outside wall surface, heat shrinkable tube